

ooming

Savanna?

Objectives

- Attendees will be able to describe how using a GIS for facilities management is an effective tool for organizing and managing construction and planning documents
- Attendees will be able to explain how maintaining an accurate inventory of classroom space can improve instructional use of a school building
- Attendees will be able to recognize an improved workflow for closeout documents that can save district staff valuable time
- Attendees will be able to describe how training maintenance staff to capture facility data will improve the quality of the data to make it relevant for the user as well as decision makers.

(GIS) GEOGRAPHIC INFORMATION SYSTEMS:

The tool we use to capture, store, process, analyze, and visualize spatial information.



GIS is an "acronym for *geographic information system*. An integ collection of <u>computer software and data</u> used to <u>view and man</u> information about geographic places, <u>analyze spatial relationsh</u> <u>model spatial processes</u>.

"A GIS provides a framework for gathering and organizing spatia related information so that it can be displayed and analyzed."


<u>www.Wiki.gis.com</u>

http://www.esri.com/what-is-gis






Issues Impacting Beaufort County School District



- Enrollment growth in some areas of county
- Excess classroom space in other areas of county
- Documentation of buildings poorly managed
- Contractor managed maintenance and custodial

Seeking a GIS Solution

- Document History of BCSD building projects
- Maintain a current "As Built" set of plans
- Manage Future Construction Project
 Documents



- Simple user Interface
- Accessible in the field
- Calculate Distances and Areas

InVision Suite

Beaufort County School District

We partnered with PenBay Solutions using an ESRI based program



For More Information on the BCSD Invision FM System or to get access please contact Carol Crutchfield at Carol.Crutchfield@beaufort.k12.sc.us or call at (843) 322-0716

- Created in the Amazon Cloud
- Negotiated an ESRI Site license
- Consolidated County GIS and BCSD data
- Developed Standards and new workflows

From this...



..to this!



Secured Log in


InVision FM	
User Name:	
Password:	
	Log In


Warning Notice. This is a Beaufort County School computer system, which may be accessed and used only for authorized BCSD business by authorized personnel. Unauthorized access or use of this computer system may subject violators to criminal, civil, and/or administrative action. All information on this computer system may be intercepted, recorded, read, copied, and disclosed by and to authorized personnel for official purposes, including criminal investigations. Such information includes sensitive data encrypted to comply with confidentiality and privacy requirements. Access or use of this computer system by any person, whether authorized or unauthorized, constitutes consent to these terms. There is no right of privacy in this system.

InVision FM is a member of the <u>InVision products and solutions suite</u> developed by <u>PenBay Solutions LLC.</u>

BCSD GIS Help Desk/Password Reset GIS Help








InVision FM M Tools County G	ilS Help	Select Level 🔻 🛦 🔍 🗶 📕 Enter Building search terms 🔍
IMPROVED WORKFLOWS and DOCUMENTATION		BUIDING INFORMATION AND DOCUMENT RETRIVAL
		Building: Pritchardville Elementary School
Building: Pritchardville Elementary School		Long Name: Pritchardville Elementary School Short Name: PVES School ID: 37
SHORTNAME PVES LONGNAME Pritchardville Elementary Sc	hool	Address:9447 Evan Way Bluffton SCYear Built:2010Cluster:BlufftonBuilding Id:PVES_78Area (SF):105,909.00Floor Count:2Condition:ExcellentHours of Operation:ExcellentLEED Level:Silver CertificateMobile Units:0.00CY Enrollment:696.00
BLDGAREA 105909.00	and to 10th grade	Sprinkler System: Links: <u>Open Building Files</u> <u>Open Demographics Files</u>
BLDGTYPE Schools and day care cente	ins to 12th grade	Open Photos and Image Files Open Site Files Open Technology Files
	<	<u>∠oom ro</u> ▼ <u>Actions</u>
CLUSTER Bluffton		
Save	EXA	MINING THE PAST

IMPROVED WORKFLOWS and DOCUMENTATION


BUIDING INFORMATION AND DOCUMENT RETRIVAL

invisionfm.beaufortschools.org - /InVisionFM/Documents/BES/Building




EXAMINING THE PAST


InVision FM	4	Tools Co	unty GIS	Help	Select L	evel 🔻 🔺	X	Enter Building	
IMPROVED and DOCUM	IEN		/S	Early Branch Yemassee	Gre Por	Jelec		QUERY REC OTHER USE	CORDS
	-	tion Grid View				_ ×			Basemaps
	Bu	ildings	611 JA	-		Export to CSV			
	S	Cluster Assi	Educatio	Building Mailing Address	Year Built	Number			>
		Beaufort	Middle	2501 Mossy Oaks Road Beaufort SC	1959	0.00		Selections	
		Battery Creek	Elementary	474 Broad River Blvd Beaufort SC	1957	0.00		Draw to Query	v to Selection
		Battery Creek	Elementary	73 Chowan Creek Bluff Beaufort SC	1963	0.00		Select Sele	
		Beaufort	Elementary	2510 Mossy Oaks Road Beaufort SC	1962	0.00		► ✓ Facility Sites	(0)
		Beaufort	Elementary	1214 Paris Avenue Port Royal SC	1911	0.00	:=	► ✓ Buildings (5)	
Query to Select					- ×			► 🗹 Rooms (0)	
Select: Buildi	ng				-			Roof Leaks (0)
 Visible Floors 		loors 🗌 Ci	urrent map ext	ent only				Roofs (0)	
Selection Method:		place 💿 Add 🔾) Subtract				K	Recreations	(0)
Facility Site		Select Facility S	Pito					Parcels (0)	
Short Name of B	uildina					•			
Full Name of Bui	-	Contains				the The			
Size of Building	-	Greater than	50000		517	TT			
Official School B	oard	Contains							
Recognized ID Building Mailing Address		Contains		0.7					
year Built		Less than	▼ 1964						
Reset		~		EXA	M	ININ	١G	THE	PAST




																																_	_																	Pro	ject	Nun	nber	:			Char	t Nun	nber:
eering specialists	OPE	•					Beaufort Elementary School													ADC-11087 M-02																																							
		r ix I			Roof Type									Base Fishng Penetrations									Drain System Perimeter												Ag	e		Estimated Cost/\$																					
Roof rea/Level	Roof Plan Drawing Number	•	Approximate Siope		Area (SQS)		Built-up Koor Aenhelt Bihimen	Coal Tar Bitumen	Modified Bittimen	enternal Deltatrathana Foam	oprayou r'uryuraurarie r'uarr		r Iperglaas reits Diver Deveded American	N You Noutinal Against	olay olayei Aceted	Cualeu	Shingles	EPDM	M etai	Granular Surfaced	Foll Faced	Smooth Surface	PVC	Thermoplastic	Pitch Pan	Plumbing Vent	Roof Relief Vent	Stack	Curb	Goose Neck	Abandoned Penetration	Pibe	Roof Draina	Overflow Drains	Conductor Head	Overflow Scubbers	Overnow acuppera	Drain scuppers		Roof Edge	Bulit-In Gutter System	Spiash Blocks	Expansion Joint	Parapet Wall	Gravel Stop/Metal Edge	Adjacent Bidg. Wall	Raised Metal Edge	Area Divider	Approximate Roof Age - Years	Life Expectancy - Years		Replacement Year		Repair			Replacement		Ånnisel Melmfananaa
A	R2		•:1		40)													X											T										X					X	-					20	D12	\$	-			120,0		\$:
B	R2 R2		4":' ":1.		78 61:		X		_	_	_	_	_	_		ĸ	_		<u>_</u>			X			-	X	-	+	-	_	_		×		-		x	_	_	_	_	_		X		X X		_				D12	\$	-		\$	10,0		\$ 3
С		2 4		2	01.	-	_	_	_	_	+	_	+	+	+	+	_		*					-	\vdash	-	┢	+	-	+	-	_	+	_	-	+	+	+	+	*	+	_			×	×		-			2	D12	\$	-		\$1,	,989,0	00	\$4,
	-			-		-	+	+	+	+	+	+	-	-	+	+	+	+	+		-		-		-	-	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+				-	-	-	+	_		+								
M	latr	rix II																						Def	fic i	ien		es										Т																					
	Damaged Membrane, Spilts/Ridges	Exposed BUR Felt Piles Bilstering of Membrane	Damaged/Deteriorated Base Flashing	Wind Scour/Damage	Bitumen Migration/Silppage/Ailigatoring	Ponding Water Evident	Lack of Spisan Pans Denetration/Tarminetion Flashings see Then S"	Pitch Pana - No Umbralias	Counterflashing Democrad (CE)		Lack of Flopel CF		Lack of Proper Flaaning	Deter Flacking Analysis	Dage Flagming, Crackeuropin. Deer Flachinge Mat Adharaf Onen Lane		_	_	Expansion Joint, Glosure of	Ponding on Coping Evident	Damaged/Deteriorated Coping/Jointe	Ceterioration of Sealants	Cracked/Damaged/Deterlorated Skylight	Debrie on Roof Guttere	Damaged Parapet Cap	Damaged Equipment	Obstructed Drainage	Damaged Roof Top Eguipment Figshings	Missing/Damaged Roof Drain Strainers	Deterioration of Shingles	Damaged Gutter (Metal)	_	-	No Protection Under Supports	-	_	Improper Kepaira	Unsecured/Unsignaged Seam Battens About and Ambridge (Instanting and About and Ambridge)	Abandoned Gurp/Equipment/Penetration	Penetration Thru/Near Panel Seam	Rusted/Deteriorated Roof Panels/Trim	Rusted/Missing/Loose Drain Fasteners		K Metal Roof Panel Finish Deterloration													emark	5	
A						_		_		\perp		\square	_		_			X	+			X					\vdash			\square	+	X	(X	4		+	\dashv	x	x			X										rcon					
	1		X	-	_		_	+	_	+	+	\square	+	_		K	+	Y	+		-	XX		-	-	-	+	+	+	+	+	×	-	-	×	-	+	+	+	$\mathbf{+}$	\mathbf{v}	_	_	x	_	-	_	_			+			ted n			e.		
B																						i 👗																	- 1	A I																			
B C					-				-				-	+	+	+		^									┢	+				1	-	-	+		+	+		-				^			-				-		FUU	rcon	ditio	n .			



MANAGING the PRESENT






MANAGING the PRESENT

20

Some of the features we are managing

- Floor plans
- Playgrounds
- Parking lots / sidewalks
- Roofs/roof leaks
- Exterior doors
 - Туре
 - Hardware
 - Access Control
- Trees
- Fire hydrants

- Security cameras
- Generators
- HVAC units
- FDC
- IT infrastructure
 - Server rack locations
 - Network switch
 - Telecom panel
- Electrical
 - Main power shut off



InVision FM

"In

-


1

9

Recomans

IMPROVED WORKFLOWS and DOCUMENTATION		The se	DOCUMENTING SPACe and SPACE USAGE	E DESIGN
	AAA		-	
and the second	Room: 211			×
	Pritchardville Eleme	ntary School 🔶 1	 ▼ 211 	
	Room Id: Building: Floor: Section/Wing: Long Name: Description: Space (As Designed): Space (As Utilized): Assignment: Assigned Teacher: Access Type: Ceiling Height: Room (SF): Capacity: Instructional Unit: Key Number: Zoom To	PVES_78_1_211 PVES 1 Classroom ECSE Classroom for ECSE Classroom Special Ed. Walker Student null 1,609.09 null Yes	Actions	
	The	1A	Edit Attributes	v1.3.0.946


MANAGING the PRESENT



By Assignment (Grades or Usage)

By Type (Classrooms, Offices, etc.)

By Access (Staff, Visitors, Students) 24



COMPARING PAST AND PRESENT

Layer Visibility

Cour

- ▶ 🗸 USGS Earthquake Service
- BC GIS Traffic Signals
- ▶ 🔽 NOAA Active Hurricane Service $\mathbf{\overline{\mathbf{v}}}$

-

T

•

 $\overline{\mathbf{v}}$

 $\overline{\mathbf{v}}$


 $\overline{\mathbf{v}}$

-

- 0

- Aerials 2013
- Aerials 2012
- ✓ Aerials 2011
- Aerials 2009
 - Aerials 2006

Aerials 2004



200 m

500 ft

COMPARING PAST AND PRESENT

Layer Visibility


Cou

✓ USGS Earthquake Service ► -**BC GIS Traffic Signals** - \checkmark ✓ NOAA Active Hurricane Service $\overline{\mathbf{v}}$ • Aerials 2013 $\overline{\mathbf{v}}$ \checkmark Aerials 2012 T Aerials 2011 • $\overline{\mathbf{v}}$ Aerials 2009 • Aerials 2006 - 0 Aerials 2004

200 m

500 ft





MANAGING the PRESENT

InVision FM

IMPROVED WORKFLOWS and **DOCUMENTATION**

KNOW YOUR NEIGHBORS: SITE PLANNING for FUTURE **EXPANSIONS**

-




Parcel: R610 036 0	00 0381 0000	-
Parcel ID:	R610 036 000 0381 0000	
Owner 1:	S C ELECTRIC & GAS CO INC	
LAND DEPAR		
Owner 2:		
Mailing Addr:	220 OPERATION WAY	
City:	CAYCE	
State:	SC	
ZIP:	29033	
Book:	1,133.00	
Page:	1,864.00	
Acres:	13.00	
Bldgs:	4.00	
Appraised:	1,748,700.00	
Assessed:	104,920.00	
LegalDescr:	- PB68 P175 *ANNEX INTO	
THE TOWN OF BL	JFFTON ORDINANCE #2000-13	
SPLIT 2/08 1.32		

Zoom To





















EMERGENCY PRE-PLANNING


Tools Print He**Secu**


InVision Secure











Implementation of Facilities Management GIS has:

- Improved workflows and documentation
- management of documents
- asset management and data creation
- access to closeout documents

Savanna?

oominad

- planning for instructional Space Planning
- emergency pre-planning for schools

Objectives Review


- Attendees will be able to describe how using a GIS for facilities management is an effective tool for organizing and managing construction and planning documents
- Attendees will be able to explain how maintaining an accurate inventory of classroom space can improve instructional use of a school building
- Attendees will be able to recognize an improved workflow for closeout documents that can save district staff valuable time
- Attendees will be able to describe how training maintenance staff to capture facility data will improve the quality of the data to make it relevant for the user as well as decision makers.

au fus ki

sland

30 km-

Savanna?





Q&A